



Phottix Mitros+ for Nikon

Firmware Version v1.15

Change Log

April 18, 2016

Changes

1. Odin II Receiver Mode support for channel 5 to 32 added
2. Support for Odin II Groups A-E (using channels 5 to 32) added
3. Odin II Digital ID Function added
4. Adjusted issues with flash head zoom when using Odin Transmitter mode.
5. Removal of flash distance display
6. Removal of triggering of Strato II receivers and Mitros+ Flashes in Strato II Receiver mode when using Odin Transmitter mode

更新

1. 新增Odin II 接收模式，新增5-32頻道
2. 支援Odin II A至E組別 (5-32頻道)
3. 支援Odin II數位ID功能
4. 修正在Odin 發射模式時變焦不能調整的錯誤
5. 移除閃光燈上的距離顯示
6. 移除在Odin TX發射模式下觸發Strato II接收器/Mitros+ Strato II接收模式的功能